

SECRET

OUT56979

1

1965 OCT 21 20 48Z

22 OCT 1965

SECRET 212036Z

1. CAMERA B 7 WAS USED IN MISSION 8850 FLOWN ON 19 OCTOBER 1965. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD WHERE NOT DEGRADED BY ATMOSPHERIC CONDITIONS.

B. 9R SIDE: FRAMES 801 TO 464 CONTAIN LONGITUDINAL MINUS DENSITY STREAKS WHICH TERMINATE AT A BREAKDOWN SPLICE IN FRAME 464. FRAME 1596 ALSO CONTAINS A BREAKDOWN SPLICE AND A MANUFACTURER'S SPLICE IS PRESENT IN FRAME 1381. PINHOLES AND SMALL EMULSION LIFTS ARE INTERMITTENT THROUGHOUT THE MATERIAL.

C. 9L SIDE: EDGE STATIC IS INTERMITTENTLY PRESENT ALONG BOTH EDGES OF THE FILM. THERE IS A ROW OF MINUS DENSITY DOTS 4 1/4" FROM THE INBOARD INBOARD EDGE AND 1 1/2" APART STARTING IN FRAME 2 AND ARE NOT DETECTABLE AFTER FRAME 16. A MINUS DENSITY STREAK IS PRESENT FROM FRAME 1479 WHERE A HEAT SPLICE WAS EMPLOYED TO FRAME 1572 WHERE ANOTHER SPLICE WAS USED. HEAT SPLICES ARE LOCATED IN FRAMES 64, 1479, 1572 AND BETWEEN FRAMES 289/290, 396/397, AND 2443/2444. THERE ARE MANUFACTURING SPLICES IN FRAMES 141 AND 2132.

D. ROLLER CHATTER WAS NOTED ALONG THE INBOARD EDGE OF BOTH SIDES OF THE MISSION. THE LAST TITLED FRAME IS 2852.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.

3. POSITIVE:

DISTRIBUTION		
Cy No.	Office	Action
1	File	
	OS	
	ADMIN	
	SEC BR	
	P & DS	
	CSD	
	IPD	
	PD	
	PSD	
	PSD-ICB	
3, 4	TID	
	IAD	
	PAG	
	DIAXX-4	
	SPAD	
	NKA-LO	
	DIA-AM	

Advance copy
Sanitized

1

Declassification Review by NGA/DoD

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

A. PI SUITABILITY WAS GOOD.

B. IN PRINTING THE DUPE POSITIVES TWO COPIES WERE MADE OF CAN 12 ON THE LEFT SIDE AND NO COPIES WERE MADE OF CAN 12 ON THE RIGHT SIDE. PROCESSING WAS GOOD.

C. CLOUDS OBSCURED OR DEGRADED APPROXIMATELY 80 PERCENT OF THE MISSION.

S E C R E T

/END OF MESSAGE/